

Demo Car Inspection Report

Vehicle Details

Make	Toyota
Model	Innova Crysta
Year	2022
Fuel Type	Diesel
Transmission	Automatic
Mileage	15,250 km

Engine & Performance

Engine Condition	Excellent
Oil Leakage	None
Noise/Vibration	Normal
Acceleration Response	Smooth

Exterior & Body

Paint Condition	Good
Scratches/Dents	Minor on left door
Headlights/Taillights	Working Fine
Glass & Mirrors	Intact

Interior

Seats & Upholstery	Clean
Dashboard	Good
AC/Heater	Working Fine
Infotainment	Functional

Tyres & Suspension

Tyre Condition	Front 80%, Rear 70%
Wheel Alignment	OK
Suspension Noise	None
Brakes	Responsive

Electricals

Battery Health	Good
Horn	Working
Indicators	OK
Wipers	Functional

Overall Remarks

The vehicle is in excellent mechanical condition with minor cosmetic imperfections. Recommended for purchase after standard servicing.